

- DC voltages are as measured with a high impedance voltmeter. Values may vary slightly due to variations between individual instruments or/and units.

CAUTION : For continued safety, replace safety critical components only with manufacturer's recommended parts (refer to parts list). Δ Indicates safety critical components. To reduce the risk of electric shock, leakage-current or resistance measurements shall be carried out (exposed parts are acceptably insulated from the supply circuit) before the appliance is returned to the customer.




V02023

Y22-3822-70

DP-M58

KENWOOD




D1~5 :1SS131 or HSS104A ED1 :10-BT-147G

DP-M58(E)(2/2)

- DC voltages are as measured with a high impedance voltmeter. Values may vary slightly due to variations between individual instruments or/and units.

CAUTION : For continued safety, replace safety critical components only with manufacturer's recommended parts (refer to parts list). Δ Indicates safety critical components. To reduce the risk of electric shock, leakage-current or resistance measurements shall be carried out (exposed parts are acceptably insulated from the supply circuit) before the appliance is returned to the customer.


Y22-3822-70




2SA95




2SB1167
2SB1168



LB1638M



2SB156




SM5875BM



BA6398FP



DTC113Z
2SA1576
2SC4081




CXD2507C




M5237ML




2SB13




CXA1782BQ




2SA954

2SB1167
2SB1168


LB1638M



2SB1565



SM5875BM



BA6398FP

DTC113ZU
2SA1576
2SC4081

CXD2507Q




M5237ML



2SB1375



CXA1782BQ



- DC voltages are as measured with a high impedance voltmeter. Values may vary slightly due to variations between individual instruments or/and units.

CAUTION: For continued safety, replace safety critical components only with manufacturer's recommended parts (refer to parts list). Δ Indicates safety critical components. To reduce the risk of electric shock, leakage-current or resistance measurements shall be carried out (exposed parts are acceptably insulated from the supply circuit) before the appliance is returned to the customer.

Y22-3822-70

DP-M58
KENWOOD